FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED May 29-17	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO.	DISTANCE FROM FIRST MANHOLE		
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		
WAS LATERAL AT CURB?			
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR		
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.			
	That deep to in it is		
SIGNED / Inspector for City	! FILED AT ENGINEER'S OFFICE		
•			

Nº 9039

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

•	MASSILLON, (OHIO, April.	5
RECEIVED OF JESSE CE	iel		FEE OF \$35,!
FOR WHICH PERMISSION IS GRANTED	e Cocil a	Ed. Hardy	une
1.7.0	SEWER ON THE	South	
Dhulin Ad. S. W.		Blackto	Ь
THE PREMISES BEING LOT NO. 136 43		HOUSE NO. 200	5
WORK TO BE DONE IN ACCORDANCE WITH ORDINA OF THE DEPARTMENT OF PUBLIC SERVICE.	NCE NO. 19-1971 D	ULY PASSED BY THE C	ITY COUNCIL, AND R

NAME OF CONTRACTOR Steinbach

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.

U-5-17 M.