FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED_ 6-13-77	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 504		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT 19' EAST OF IT 11' DE F P CURB LINE AND DEPTH	
WAS LATERAL AT CURB? VES	NAME OF CONTRACTOR EAR/ G/ick	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR FART GILCH	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
V 4-		
	T'DEEP	
	34	
	14'	
0 < 19 ,	IN DEED	
SIGNED William Hammer	FILED AT ENGINEER'S OFFICE	
Inspector for City		
REMARKS		

Nº 9060

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

√ 1 X.√	massillon, ohio, June 1. leck fee of 25
RECEIVED OF EASTER END	HO B
OR WHICH FERMISSION IS GRANTED	2 det
of You are h. E AVE.	ER ON THE 1870 CRUBY Soul
THE PREMISES BEING LOT NO 12553	HOUSE NO. 504
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO.	

OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR EUR SULEK

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.