

✓
**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
 AND SIGNED WHEN RETURNED**

Nº 9063

DATE INSPECTED May 177

IF SO HOW AND LOCATION FROM
 FIRST MANHOLE DOWN STREAM

HOUSE NO. 1226

SIZE OF PIPE USED Cast iron


DISTANCE FROM FIRST MANHOLE
 DOWN STREAM TO DITCH AT
 CURB LINE AND DEPTH

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



*They put 8 feet of Cast iron to
 new part of Building for one Bathroom*

SIGNED _____

A H. 8

Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 9063

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, JUNE 6

RECEIVED OF HOLDERBAUM FEE OF \$0.00

FOR WHICH PERMISSION IS GRANTED CAROL KRAFT

TO TAP SEWERS SEWER ON THE EAST

OF DUNKAN AVE. ST. TYPE OF STREET CHIP & SEAL

THE PREMISES BEING LOT NO. 4079, HOUSE NO. 1226

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RESOLUTION NO. 19-1971 OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR HOLDERBAUM

Note: This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.