FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

9071

DATE INSPECTED AOU = 27	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?		
WAS ATTACHED TO MAINSHOW BY DIAGRAM RELATION OF LATERAL TO WA		
920 Record or	nebedy linene	.*
<i>e</i> ,	and the second s	
signed James inspector for City	FILED AT ENGINEER'S OFFICE	

OFFICE OF THE DIRECTOR OF PUBLIC SER' PERMIT TO TAP SEWER

	MASSILLON, OHIO,	20
RECEIVED OF 7/20/2 Conf	·	FEE OF \$
FOR WHICH PERMISSION IS GRANTED THE COL	\mathcal{L}_{i}	
TO TAP A SEV		
of Callell La SIE. AVE. ST. TY		
THE PREMISES BEING LOT NO. 1374 8	#	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO OF THE DEPARTMENT OF PUBLIC SERVICE.). 19-1971 DULY PASSED BY	THE CITY COUNCIL, AND RI
NAME OF CONTRACTOR 71.4600.000		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.