

✓  
N<sup>o</sup> 9094 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED Oct 6 - 77 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 327 319 RD


HOUSE NO. 1132

SIZE OF PIPE USED 6 DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH \_\_\_\_\_

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR \_\_\_\_\_

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED \_\_\_\_\_ 9-1-78 FILED AT ENGINEER'S OFFICE \_\_\_\_\_  
Inspector for City

REMARKS \_\_\_\_\_

Nº 9094

OFFICE OF THE DIRECTOR OF PUBLIC SER  
PERMIT TO TAP SEWER

MASSILLON, OHIO, August 24

RECEIVED OF

George Lindsay

FEE OF \$

15.

FOR WHICH PERMISSION IS GRANTED

George Lindsay II

TO TAP

Sewer

SEWER ON THE

North

OF

Road Ave. N.E.

AVE.

ST. TYPE OF STREET

Black Top

THE PREMISES BEING LOT NO.

11240

HOUSE NO.

1122

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND R  
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Lindsay

Note: This permit covers work outside of building only. Any work  
walls of building is subject to Massillon Board of Health Regulations.