FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

 $N_{\bar{0}}$

9099

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO	DISTANCE FROM FIRST MANHOLE		
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		
WAS LATERAL AT CURB?			
WAS ATTACHED TO MAINSHOW BY DIAGRAM RELATION OF LATERAL TO WAI	NAME OF CONTRACTORL OF BUILDING SERVED.		
House toin	down plund at Cossmer		
SIGNED Inspector for City	FILED AT ENGINEER'S OFFICE		
REMARKS			

Nº 9.099

OFFICE OF THE DIRECTOR OF PUBLIC SER' PERMIT TO TAP SEWER

	*		
	MASSILLON, OHIO,	5-2- p. 2	, :
RECEIVED OF COLUMN A	Sows	·	FEE OF \$ 1.
FOR WHICH PERMISSION IS GRANTED	<u> </u>	Merre	alio
CUT OFF SANITARY	SEWER ON THE	57.3-14	
of St. St.			
THE PREMISES BEING LOT NO. 16757	, Hous	se no	<u> </u>
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE OF THE DEPARTMENT OF PUBLIC SERVICE.	E NO. 19-1971 DULY F	PASSED BY THE C	ITY COUNCIL, AND RI
NAME OF CONTRACTOR		**************************************	

Note: This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.