FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

 $N^{\underline{0}}$

9107

	·				
DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM				
HOUSE NO.					
	DISTANCE FROM FIRST MANHOLE				
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH				
WAS LATERAL AT CURB?					
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR				
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.					
2					
House done	yu				
- no record					
+ 45	· · · · · · · · · · · · · · · · · · ·				
SIGNED Inspector for City	FILED AT ENGINEER'S OFFICE				
REMARKS					

OFF

№ 9107

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

		MASSILLON, (ohio,	:
RECEIVED OF	<u> </u>	<u> 5000</u>		FEE OF \$
FOR WHICH PERMISSION I	S GRANTED	71	12014 OF	
TO TAP	999 <u>0</u> 9	SEWER ON THE		
0F/214224 43		AVE. ST. TYPE OF STREET		Angulates
THE PREMISES BEING LOT	· NO. 2050 27	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	HOUSE NO.	<u> </u>
WORK TO BE DONE IN ACC		NCE NO. 19-1971 D	ULY PASSED BY THE	CITY COUNCIL, AND RU

Note: This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.