№ 9122

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED Much 5 78	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 2003	
SIZE OF PIPE USED 6	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? Passed Curb	NAME OF CONTRACTOR MUSICAL
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR TURE OF
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	House one 30° And 16 with East ainer 3 fet east of porch
1 # \$	10 feet cleep
SIGNED Inspector for City	FILED AT ENGINEER'S OFFICE
DEMARKS	

Nº 9122

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON,	оніо, // л	vi. d	
RECEIVED OF Liney Bras.				OF S 25.
FOR WHICH PERMISSION IS GRANTED Live	of Bus.	•	,	5. V.
TO TAB Sarulary	•	Sa	uth	
of Cakhill Cir. W. AVE ST.	and the second s	Chi	of de	<u> </u>
THE PREMISES BEING LOT NO. 13716		1.	2003	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE OF THE DEPARTMENT OF PUBLIC SERVICE.	E NO. 19-1971 D	ULY PASSED BY	THE CITY COU	NCIL, AND F
NAME OF CONTRACTOR Malanite				
NAME OF CONTRACTOR				

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.