## **Nº** 9123

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
House No.	DISTANCE FROM FIRST MANHOLE	
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?		
WAS ATTACHED TO MAIN NAME OF CONTRACTORSHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
House toin	down pluged at lasena	
SIGNED Inspector for City	FILED AT ENGINEER'S OFFICE	
	· · · · · · · · · · · · · · · · · · ·	

Nº 9123

## OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

· · · · · · · · · · · · · · · · · · ·	iassillon, ohio, 1120 - 10
RECEIVED OF lasyh Jeffinis	FEE OF \$ 5. U
FOR WHICH PERMISSION IS GRANTED ALLE	he Steel
CUT- OF F Sanitary SEWE	
OF 4# 11. S. C. AVE. ST. TYPE	
THE PREMISES BEING LOT NO. 2895	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. OF THE DEPARTMENT OF PUBLIC SERVICE.	19-1971 DULY PASSED BY THE CITY COUNCIL, AND R
NAME OF CONTRACTOR Jufficies	
H = H + H + H + H + H + H + H + H + H +	stride of building only. Any would

Tues. 11-15

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.