

9-
L

Nº 9137

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED Dec 29 -77

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. _____

SIZE OF PIPE USED 6 in

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN _____


NAME OF CONTRACTOR Benda

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

House

5 Feet in from south EAST corner

Boiler
7 1/2 feet deep
STARK and 30° BOV
Side Walk



SIGNED _____

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS _____

Relay of Lateral

No 9137

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO

Dec. 29

RECEIVED OF

Cemmins Flourens

FEE OF

25.

FOR WHICH PERMISSION IS GRANTED

A. J. Diana

TO TAP

Sanitary

SEWER ON THE

North

OF

Lincoln Way West

AVE.

ST. TYPE OF STREET

Hard Surface

THE PREMISES BEING LOT NO.

10198

HOUSE NO.

2944

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND R
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

A. J. Diana

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.