Nº 9142

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO	DISTANCE FROM FIRST MANHOLE
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAINSHOW BY DIAGRAM RELATION OF LATERAL TO WAL	NAME OF CONTRACTOR L OF BUILDING SERVED.
#	
SIGNED	FILED AT ENGINEER'S OFFICE
Inspector for City	

OFFICE OF THE DIRECTOR OF PUBLIC SER
PERMIT TO TAP SEWER

ŧ-	MASSILLON, OHIO, Much 3
ils	RECEIVED OF HT W. Cont nador FEE OF 550
	FOR WHICH PERMISSION IS GRANTED OUT DA Sanit, Sa
P	TO TAP CUL SEWER ON THE West
•	OF LOST AL TISE ST. TYPE OF STREET THOUSE SWIFE
	THE PREMISES BEING LOT NO. 9780, HOUSE NO. 879
	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND R

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND I OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR TY W Confidence

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.