

Repair

N^o 9166

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 5-23-78

IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM x 114 feet to ②

HOUSE NO. 443

SIZE OF PIPE USED 4"

DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? yes


WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Holden

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Roots in by main

R. lateral in top one is closed bottom is line



SIGNED J. H. 8

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS _____

REPAIR

2
No 9166

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO,

May 12

RECEIVED OF

Holderbaum

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

Holderbaum

TO TAP

Sanitary

SEWER ON THE

West

OF

8TH St. N.E.

AVE.

ST. TYPE OF STREET

Chip & Seal???

THE PREMISES BEING LOT NO.

908

HOUSE NO.

443

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND R
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Holderbaum

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.

Monday