185

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED They 31 18	F SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 13/1	
SIZE OF PIPE USED 6	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 1-
WAS LATERAL AT CURB? 15 fut will	
WAS ATTACHED TO MAIN,	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
	We poch 18 feet in from northwest and
	Frein 15 but behand out
SIGNED 1+1	2 0 14 5 W
/ Inspector for City	

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

		оню,	1
RECEIVED OF	aptitude	FEE OF \$	5.
FOR WHICH PERMISSION IS GRANTED	head died	<i>V</i>	,
TO TAP Annatary			
of 203/28/22/2		,	
THE PREMISES BEING LOT NO. / 34			
WORK TO BE DONE IN ACCORDANCE WITH OF THE DEPARTMENT OF PUBLIC SERVICE.			1D F
NAME OF CONTRACTOR			

Note: This permit covers work outside of building only. Any work

walls of building is subject to Massillon Board of Health Regulations.