DATE INSPECTED ON H 78	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. Main	
SIZE OF PIPE USED Size	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN POTA PACE	NAME OF CONTRACTOR Distin
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
150 feet to clean and 2414	
- rotat off hour	115 Rut France
(A) "SH Wis	Reit of Series
SIGNED IN FRONT & 2414 Inspector for City	FILED AT ENGINEER'S OFFICE
/_A\/	

Nº 9211

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

3 ·	MASSILLON, OHIO, Jy. 4- 28
ch	RECEIVED OF A A Carra FEE OF \$
Ine S. W.	FOR WHICH PERMISSION IS GRANTED Albut Glick
	TO TAP Saintary SEWER ON THE Windling aw.
garante e en en en en en e _{n en e}	OF Windling am, SVV. AVE. ST. TYPE OF STREET Chip of Sul
	THE PREMISES BEING LOT NO. Thank 14087, HOUSE NO. 2414
	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE SITY COUNCIL, AND R
ent	OF THE DEPARTMENT OF PUBLIC SERVICE. NAME OF CONTRACTOR. Diana
CRI.	Note: This permit covers work outside of building only. Any work

walls of building is subject to Massillon Board of Health Regulations.