FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
$N^{\circ}$ 9215 AND SIGNED WHEN RETURNED
2, 7 E
DATE INSPECTED (CCT 3 79) IF SO HOW AND LOCATION FROM 183 feet Gift FIRST MANHOLE DOWN STREAM 183 feet
HOUSE NO. 130 8
DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH
WAS LATERAL AT CURB? 15 feel behione
WAS ATTACHED TO MAINNAME OF CONTRACTOR Stain fracts
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
House 19 feet from southwest corner
Red 1)
of lest deep
SIGNED 183  RUTH VI SW FILED AT ENGINEER'S OFFICE
Inspector for City

REMARKS

## Nº 9215

## OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON,	оню, Ост.	<u> </u>	
RECEIVED OF July Cice	,r			
FOR WHICH PERMISSION IS GRANTED	Cecil			
TO TAP Sanitary	SEWER ON THE	Cast	•	
of 10± It IW.			and a	
•		, HOUSE NO.	•	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND				
OF THE DEPARTMENT OF PUBLIC SERVICE.				
NAME OF CONTRACTOR SHOWN THE			•	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.