9217

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED CLOTH - 78	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	150 feet Shadling
HOUSE NO. 25		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? 10		$n \cdot n \cdot n$
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	Slick
SHOW BY DIAGRAM RELATION OF LATERAL TO WA	LL OF BUILDING SERVED.	7
of the	104 feet to pour 3 feets	19 feet brown northwest Corner
150		Corner
SIGNED Hinspector for City	FILED AT	ENGINEER'S OFFICE

Nº 9217

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

MASSILLON, OHIO, Oct. 2	MASSILLON, OHIO, CCC 2	
RECEIVED OF A Chief Stick	FEE OF \$35.5	
FOR WHICH PERMISSION IS GRANTED Albut Stuck - Bayd Par	Peternan	
TO TAP Janutary SEWER ON THE Thurt	<u> </u>	
OF 34 50 NV AVE. ST. TYPE OF STREET Chep of Seal		
THE PREMISES BEING LOT NO. 14096 3813, House No. 57		
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CIT OF THE DEPARTMENT OF PUBLIC SERVICE.		

LL CALL

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.