FOLLOWING DATA TO BE ANSWERED BY INSPECTOR 9252 AND SIGNED WHEN RETURNED

 $N_{\bar{0}}$

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL	TO WALL OF BUILDING SERVED.
•	
•	
•	
SIGNED	for City FILED AT ENGINEER'S OFFICE
Inspector	for City

 N^{0} 9252

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON, OHIO, fame 4 feb. 7				J
RECEIVED OF Beauty					
				- 	
FOR WHICH PERMISSION IS GRANTED	-1 Seizeld	الي مد موسد الذي 			
our of Santy	SEWER CN	THE	ر المساريسط أيمر		
OF					
THE PREMISES BEING LOT NO. 144		, HO	use no	1209	
WORK TO BE DONE IN ACCORDANCE WITH ORDI	NANCE NO. 19-19	971 DUL	Y PASSED BY	THE CITY COUNCIL, AN	ID RI
OF THE DEPARTMENT OF PUBLIC SERVICE.					
NAME OF CONTRACTOR BULL					

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.