

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

N^o 9258

DATE INSPECTED March 29 - 79

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 611

SIZE OF PIPE USED 6


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? 15 feet behind

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Haulbush

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



*put 40 feet new line in
Repair field for with gravel*

611 SHEET

SIGNED _____

JAF

Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 9258

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO,

March 20

RECEIVED OF

Michael Morris

FEE OF \$

FOR WHICH PERMISSION IS GRANTED

Repair Sanitary

TO TAP

Repair

SEWER ON THE

South

OF

611 Shore NE

AVE.

ST. TYPE OF STREET

Chip & Seal

THE PREMISES BEING LOT NO.

11509

HOUSE NO.

611

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Robert L. Lamm

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.