## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Nº 9308 AND SIGNED WHEN RETURNED

DATE INSPECTED	ID LOCATION FROM DLE DOWN STREAM					
HOUSE NO		OM FIRST MANHOLF				
SIZE OF PIPE USED	DOWN STREAM CURB LINE A	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH				
WAS LATERAL AT CURB?						
		NAME OF CONTRACTOR				
SHOW BY DIAGRAM RELATION OF LA	TERAL TO WALL OF BUILDING	3 SERVED.				
SIGNED		City FILED AT ENGINEER'S OFFICE				
Ins	pector for City					

Nº 9308

## OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

		MASSILLON, OHIO.	Just 1	0
RECEIVED OF	slucy & Sa	no	00	FEE OF \$ 2/0 7
RECEIVED OF	City	Maxillan	U	•
OT TO THE Santany	SEV	VER ON THE	South	
of Turnant Uni.			and the second s	
THE PREMISES BEING LOT NO	1108	, Hous	E NO. 19	
WORK TO BE DONE IN ACCORDANCE OF THE DEPARTMENT OF PUBLIC SE		). 19-1971 DULY P	ASSED BY THE CITY	COUNCIL, AND R
NAME OF CONTRACTOR	luch			

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.