


142



FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 9315

DATE INSPECTED 11-11-79 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 156'
HOUSE NO. 1729? - 1727
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 156'
WAS LATERAL AT CURB? no
WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR Malwitz
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED William Blundon Inspector for City FILED AT ENGINEER'S OFFICE

REMARKS Manhole in Rear of 1805-

14 50
Nº 9315

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, Aug. 21

RECEIVED OF

Thomas Laughlin

FEE OF \$ 25.

FOR WHICH PERMISSION IS GRANTED

Thomas Laughlin

TO TAP

Sanitary

SEWER ON THE

South

OF

Woodruff Ave. N.W.

AVE.
ST.

TYPE OF STREET

Chap. & Seal

THE PREMISES BEING LOT NO.

1727

14141
0.1.352

HOUSE NO.

1727
1729

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RESOLUTION NO. 19-1971 OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Malanite

Note: This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.