Nº 9320 FOLLOW

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9-7-79	IF SO HOW AND LOCATION FROM 36 /	
HOUSE NO. 2516		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? 7100	7-1	
WAS ATTACHED TO MAIN 1200	NAME OF CONTRACTOR Fature	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
HOUSE N HOUSE 481 TO HOUSE		
HOUSE 481 TO HOUSE 30 Degra Band 121 #N FROM CURB 8 DEEP SO FROM MANHOLE		
SIGNEDLY Window FILED AT ENGINEER'S OFFICE		
Inspector for City		
DEMARKS		

№ 9320

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON, OHIO,
RECEIVED OF John Kranichy FOR WHICH PERMISSION IS GRANTED John Wa	FEE OF \$ 25.
FOR WHICH PERMISSION IS GRANTED JAMES HA	inavaly
TO TAP Sanctary SEV	
of Markoward Jani JE AVE.	DE LE STREET CHIST Shel
THE PREMISES BEING LOT NO. 14021	, HOUSE NO. 2516
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO	
NAME OF CONTRACTOR Lawrence	-

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.