

2-6

N^o 9338

✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 12-5-79

IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 246'

HOUSE NO. 611-613

SIZE OF PIPE USED 4"


DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 246'

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Holdevaun

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED



WALLACE AVE S.E.

← (initials)

SIGNED William Blanton
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Repair
Nº 9338

OFFICE OF THE DIRECTOR OF PUBLIC SER
PERMIT TO TAP SEWER

MASSILLON, OHIO, *Dec. 4*

RECEIVED OF *Holdenbaum* FEE OF \$ *25.*

FOR WHICH PERMISSION IS GRANTED *Wilbarger*

TO TAP *Sanitary* SEWER ON THE *South*

OF *Wallace Ave. S.E.* AVE. ST. TYPE OF STREET *Hard Surface*

THE PREMISES BEING LOT NO. *1546*, HOUSE NO. *611-613*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND R
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Holdenbaum*

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**