

N^o 9341

✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED_____

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM_____

HOUSE NO. _____

SIZE OF PIPE USED _____

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

SIGNED _____

Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

House torn down

BETWEEN
3RD & 4TH

CUT-OFF

No 9341

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

2:35
1:16

MASSILLON, OHIO, Dec 4

RECEIVED OF Bennett & Son FEE OF \$ 5.00

FOR WHICH PERMISSION IS GRANTED Republic Steel Corp.

CUT-OFF Sanitary TO TAP SEWER ON THE South

OF Sanitary Road AVE. ST. TYPE OF STREET Blind Tap

THE PREMISES BEING LOT NO. 1888, HOUSE NO. 315

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RESOLUTION NO. 19-1971 OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Bennett

Note: This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.