FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 2-26-80	IF SO HOW AND LOCATION FROM 36 7	To Second	manhe
HOUSE NO. 501-Cheny No M.W.		······································	17
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		
WAS LATERAL AT CURBY MAN HOLE			÷
WAS ATTACHED TO MAIN MAN HOLE	NAME OF CONTRACTOR J. J. D. Lan	<u>~a</u>	
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.	•	
· @ 10'A7	FIRST MANIFICE PIPE PERST LAST IRON PERST INDO PERST		
\s\ 	LRON.		
The state of the s			
	pe cas'		
6 6 20 6 P	101		
	100.		
	Marie Contraction of the Contrac		
//			
/110m /1), dim	WEAT BUILDING		
SIGNED Inspector for City	FILED AT ENGINEER'S OFFICE		
1.7	1	4	
DEMARKS Mouth Cement a	? O .	, M [®]	

 N^{0} 9353

4 12415

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON, OHIO, Felt. 13	<u>,</u>
RECEIVED OF A D. Mining		
FOR WHICH PERMISSION IS GRANTED 145 7		
TO TAP Adminary SE	WER ON THE	k.=±)
OF CALLY AT ST. TY 5th ST NW	PE CF STREET	
THE PREMISES BEING LOT NO. 2.1.98	, House No	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE N OF THE DEPARTMENT OF PUBLIC SERVICE.	O. 19-1971 DULY PASSED BY THE CITY	COUNCIL, AND R
NAME OF CONTRACTOR		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.