

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 9361

DATE INSPECTED 4-16-80

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 826

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR East 30

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

826

12' TO WALL OF
HOUSE ON WEST SIDE

62' FROM HALLTISE,

EDGE OF PAVEMENT TO SEWER PLUGED

SIGNED William Windsor
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS House torn down

15 22

CUT-OFF

Nº 9361

OFFICE OF THE DIRECTOR OF PUBLIC SER
PERMIT TO TAP SEWER

MASSILLON, OHIO, April 11

RECEIVED OF East 30 Spermating FEE OF \$ 5.00

FOR WHICH PERMISSION IS GRANTED Edward Lang

TO TAP Sanitary SEWER ON THE North

OF West Ct. S.E. AVE. ST. TYPE OF STREET City & Sub

THE PREMISES BEING LOT NO. 10042, HOUSE NO. 816

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND R
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR East 30

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.