


N^o 9371

✓
 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
 AND SIGNED WHEN RETURNED

DATE INSPECTED 5-14-80IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAMHOUSE NO. 945SIZE OF PIPE USED 6"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTHWAS LATERAL AT CURB? yesWAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Just-Bliss

24' TO HOUSE — 8 PIPE
 28' IN TO WHERE HE TAPPE.
 1'4' IN FROM CURB TO BUILT IN

ⓂH

50' FROM

Manhole

SIGNED

William Windsor

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

House hasnt been built yet

Nº 9371

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 11-5-71

RECEIVED OF _____ FEE OF \$ _____

FOR WHICH PERMISSION IS GRANTED _____

TO TAP main SEWER ON THE West

OF 1st AVE.
ST. TYPE OF STREET 1st

THE PREMISES BEING LOT NO. _____, HOUSE NO. 100

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND IN
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR _____

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**