FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED $7-9-80$	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?	NAME OF CONTRACTOR Holderbaum Seven Co.	
WAS ATTACHED TO MAIN		
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
143/DEEP		
(-/2)		
1 FC 41/2	WEEP	
SIGNED William ZUL	N W.E. = indom filed at engineer's office	
Inspector for City		

№ 9377

OF THE DEPARTMENT OF PUBLIC SERVICE.

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

MASSILLON, OHIO, June 30	
DECEMBED OF GLOSA Craft art Studio FEE OF 5 25	<u>-</u>
FOR WHICH PERMISSION IS GRANTED & lass Craf and Studio	
TO TAP Santary SEWER ON THE South	
OF Jin Coln May East St. TYPE OF STREET Hard Surface	1
THE PREMISES BEING LOT NO 10406 , HOUSE NO. 1809	
V V	

IAME OF CONTRACTOR SOLVEY AND COLORS ALLEN

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.