FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

 $N^{\underline{o}}$ 

	ATE INSPECTED 20-16-80	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HO	OUSE NO. 9/0	,,	
3 51	IZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH  DEPTH  5	
1 6 6	AS LATERAL AT CURB?		
, "W	AS ATTACHED TO MAIN	NAME OF CONTRACTOR	
	SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
1,			
W	1 HOUSE 4' DEED AT HOUSE		
10-44-001	35 OF PIETO HOUSE 300 BEND HOUSE		
	105 FROM MANHOLE		
1 (MH)	FIRE HYD. @ O'D' A BOND S'AT LATERAL		
	STATENE 21 IN FROM MAIN		
SI	SIGNED William Windom FILED AT ENGINEER'S OFFICE		
	Inspector for City		
	REMARKS LATERAL COMES IN FROM CURB 106"		
RE	EMARKS LHICKEL COM	ES 110 F- ROM CO / 13 10 6	

BETWEED

9TH + 10TH

2-33

2-44

**№** 9392

## OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON, OHIO, Supt. 30		
سيسق / سيا	<i>U</i> <del></del>		
FOR WHICH PERMISSION IS GRANTED Gall ().	3 acuin		
TO TAP Sometary SEW	ER ON THE MATE		
OF Stale Gree 118 AVE. ST. TYP	ECF STREET Blackty		
THE PREMISES BEING LOT NO. 1246	<i>V</i>		
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RI OF THE DEPARTMENT OF PUBLIC SERVICE.			
NAME OF CONTRACTOR 4.8 7%.			

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.