

Nº 9419

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 12-1-80

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1862

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR

HOLGER BAUM

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

3' FROM
WEST CORNER OF
HOUSE
1862
8' AT HOUSE
8' AT LATERAL
50' PIPE
TRENCH S.E.

N
W
S
E

SIGNED RICHARD J. CRENSHAW
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 9419

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO,

Mar. 26

RECEIVED OF

Haldubaum

FEE OF \$

25.

FOR WHICH PERMISSION IS GRANTED

Virgil Wilson

TO TAP

Sanitary

SEWER ON THE

Main

OF

Summit Ave., S.E.

AVE.

ST. TYPE OF STREET

East Dayton

THE PREMISES BEING LOT NO.

13435

, HOUSE NO.

1864 1866

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND R
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Haldubaum

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**