

Nº 9420 ✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM. 150'

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 150


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH_____

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN 22

NAME OF CONTRACTOR 1010510000

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED _____

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

REMARKS 6' EAST OF SEAM TO HULL AT 122
Replaced ONE 6" PIPE AT 115

2 12

Repair

Nº 9420

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, *Dis. 8*

RECEIVED OF *Holbrook*

FEE OF \$ *15.*

FOR WHICH PERMISSION IS GRANTED *Virgil Macmillan*

TO TAP *Limbsing*

SEWER ON THE *Hotel*

OF *2742 1/2*

AVE.

ST. TYPE OF STREET *City & Ave*

THE PREMISES BEING LOT NO. *2354*

HOUSE NO. *115-117-119*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND R
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Holbrook*

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**