


**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH_____

NAME OF CONTRACTOR

19' FROM EAST
CORNER OF
BUILDING



SIGNED _____ FILED AT ENGINEER'S OFFICE _____
Inspector for City

REMARKS

25 UNITS

how many appts.

N^o 9421

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, DEC. 8

20. RECEIVED OF GIBBONS + GRABLE FEE OF \$ 25

15. FOR WHICH PERMISSION IS GRANTED GIBBONS + GRABLE

TO TAP SANITARY SEWER ON THE NORTH

OF TREMANIT AVE. ST. TYPE OF STREET CHURCH

3 (LINCOLN WAY) 10421, 22, 23
THE PREMISES BEING LOT NO. 1928 HOUSE NO.

175) WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

12E NAME OF CONTRACTOR GIBBONS + GRABLE

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.