

9422 ✓

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED9:30  
✓

DATE INSPECTED

P

IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM

HOUSE NO.

2210-12-14-16-18

SIZE OF PIPE USED

6'

DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH

WAS LATERAL AT CURB?


2

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

Holderbaum

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

William Hammer

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

N<sup>o</sup> 9422

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE  
PERMIT TO TAP SEWER

MASSILLON, OHIO, Dec. 9

RECEIVED OF Haldubauer FEE OF \$ 2.5

FOR WHICH PERMISSION IS GRANTED William Christoff

TO TAP Saintary SEWER ON THE North

OF Hank Ave. S.E. AVE. ST. TYPE OF STREET Blacktop

THE PREMISES BEING LOT NO. D. H. 326, HOUSE NO. 2210-12-14-16-18

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND  
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Haldubauer

**Note: This permit covers work outside of building only. Any work  
walls of building is subject to Massillon Board of Health Regulations.**