

9424 ✓

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNEDDATE INSPECTED 3-11-81IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAMHOUSE NO. 1835

SIZE OF PIPE USED

6"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB?

No

WAS ATTACHED TO MAIN


No

NAME OF CONTRACTOR

HOLDERBAUM

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N ↗



SIGNED

William Hammer
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

EAST

8 F.

16711

9-30

Nº 9424

OFFICE OF THE DIRECTOR OF PUBLIC SEW
PERMIT TO TAP SEWER

MASSILLON, OHIO, March 4

RECEIVED OF Haldubauer FEE OF \$ 25

FOR WHICH PERMISSION IS GRANTED Standard Luting Lab., Inc.

TO TAP Sanitary SEWER ON THE South

OF Harold Ave. S.E. AVE. ST. TYPE OF STREET Blacktop

THE PREMISES BEING LOT NO. O.L. 454, HOUSE NO. 1835

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Haldubauer

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**