

9427 ✓


20-1
FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNEDDATE INSPECTED 6-23-81IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAMHOUSE NO. 1938SIZE OF PIPE USED 6"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH38' EAST OF MH 9' DEEPWAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

Glick

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N
↑38'

SIGNED

William Hammer

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Sumner
N^o 9427

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, *March 20*

RECEIVED OF *Jacob Glick*

FEE OF \$ *2*

1.E.
FOR WHICH PERMISSION IS GRANTED *Jacob Glick*

TO TAP *Sanitary*

SEWER ON THE *North*

OF *Hickory Ave 1.E.*

AVE.

ST. TYPE OF STREET *Chip & Seal*

THE PREMISES BEING LOT NO. *14081*

HOUSE NO. *1938*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

e
NAME OF CONTRACTOR *Jacob Glick*

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.