9428

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 7-25-8/	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO. 1805			
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 130' WEST OF MIOODEER		
WAS LATERAL AT CURB? V 5	,		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR CFC/		
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.			
	110 A		
and the second s	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
	30083 1010		
	180 = R		
SIGNED William Banner Inspector for City	FILED AT ENGINEER'S OFFICE		
··· • • • • • • • • • • • • • • • • • •			

√º 9428

OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

	MASSILLON, OHIO, A	int 3
RECEIVED OF Sexce Civil		FEE OF \$
FOR WHICH PERMISSION IS GRANTED Juce C	Ecil	
1 -, ()	WER ON THE	acth
OF Ohulin Rd. S. W. AVE. TO		tackTob
THE PREMISES BEING LOT NO. 14003		
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE N		
OF THE DEPARTMENT OF PUBLIC SERVICE.		
NAME OF CONTRACTOR		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.