Nº 9462 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

		IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
٠	HOUSE NO			
	SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		
	WAS LATERAL AT CURB?			
	WAS ATTACHED TO MAIN			
	SIGNED NO INSPECTION Inspector for City	FILED AT ENGINEER'S OFFICE		
	PELLAPIA			

Nº 9462

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON,	OHIO, April	15,
RECEIVED OF CHANGE	fairs		FEE OF \$
FOR WHICH PERMISSION IS GRANTED	truck Order	I Facles	
CHI-DET STATES			
OF Photos also IV.			3
THE PREMISES BEING LOT NO. $3//$		- //	
WORK TO BE DONE IN ACCORDANCE WITH ORDI			
OF THE DEPARTMENT OF PUBLIC SERVICE.			
NAME OF CONTRACTOR Little			

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.