

Nº 9473

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

REPAIR

DATE INSPECTED 6-30-82

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

67' South of MH 5'D

HOUSE NO. 407 9th ST S.W.

SIZE OF PIPE USED 4"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR JIM PLAS.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

→ N



SIGNED

William Hammer

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

REPAIR

Nº 9473

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, JUNE 29

RECEIVED OF PAUL HALTER FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED PAUL HALTER

TO TAP REPAIR SANITARY SEWER ON THE WEST

OF 3TH ST. S.W. AVE. ST. TYPE OF STREET HARD SURFACE

THE PREMISES BEING LOT NO. 9915, HOUSE NO. 407

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Jim PLAS

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.