

Nº 9491

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED**

20-41✓

DATE INSPECTED 9-15-82

IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1320

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH


WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN No

NAME OF CONTRACTOR LASURE

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N  
↑



SIGNED William Hammer  
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Tim BRUMMAGE

N<sup>o</sup> 9491

OFFICE OF THE DIRECTOR OF PUBLIC SER  
PERMIT TO TAP SEWER

MASSILLON, OHIO, Sept 2

RECEIVED OF

Tim Brummage

FEE OF \$ 2

FOR WHICH PERMISSION IS GRANTED

Lasare Excavating

TO TAP

Sanitary

SEWER ON THE

East

OF

Meadowbrook SW

AVE

ST. TYPE OF STREET

Cherry Seal

THE PREMISES BEING LOT NO.

12934

HOUSE NO.

1320

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND  
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Lasare Excavating

Note: This permit covers work outside of building only. Any work  
walls of building is subject to Massillon Board of Health Regulations.