FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED: 10 - 28 - 82	IF SO HOW AND LOCATION FROM 77' EAST OF ME 7'DEEP
SIZE OF PIPE USED C"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	NAME OF CONTRACTOR 13/85
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	· · · · · · · · · · · · · · · · · · ·
	1810
	0 77. X 27.

SIGNED William Hammer FILED AT ENGINEER'S OFFICE

EMARKS _____

Nº 9501

OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

	MASSILLON, OHIO,	I 20
RECEIVED OF Plantite		
FOR WHICH PERMISSION IS GRANTED MANGEY	- //	
TO TAP Sanitary SE	WED ON THE	reth:
OF 1 Hand Hand 716 AVE. ST. TY		
THE PREMISES BEING LOT NO. 10 157 - 88	· · · · · · · · · · · · · · · · · · ·	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE N		
OF THE DEPARTMENT OF PUBLIC SERVICE.		
NAME OF CONTRACTOR		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.