

N^o

9503

✓
✓
FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED

11-5-82

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO.

1301

SIZE OF PIPE USED

6"

4P

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

15' EAST OF MH 9' DEEP

WAS LATERAL AT CURB?

YES


WAS ATTACHED TO MAIN

—

NAME OF CONTRACTOR

WENGER

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

William Hammer
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 9503

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, Nov. 1

RECEIVED OF Menger Excavating FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED Hydro - O - Shift (Industrial)

TO TAP Sanitary SEWER ON THE South

OF Sanders Ave S.W. AVE. ST. TYPE OF STREET R.R. Top

THE PREMISES BEING LOT NO. 14122, HOUSE NO. 13015

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Menger

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.