

Nº 9506

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 11-30-82

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1004

SIZE OF PIPE USED 4"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB?

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

Holderbaum

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

REPAIR

SIDEWALK

SIGNED

William Harmon
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

REPAIR

Nº 9506

OFFICE OF THE DIRECTOR OF PUBLIC SER
PERMIT TO TAP SEWER

MASSILLON, OHIO, Nov. 23

RECEIVED OF Waldbaur FEE OF \$ 25

FOR WHICH PERMISSION IS GRANTED William J. Ingus

REPAIR TO TAP Sanitary SEWER ON THE North

OF Mill Gr. W.E. AVE. ST. TYPE OF STREET Chip & Seal

THE PREMISES BEING LOT NO. 10121, HOUSE NO. 1004

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Waldbaur

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**