

Nº 9507

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 12-2-82

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 112

SIZE OF PIPE USED 4"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? —



WAS ATTACHED TO MAIN —

NAME OF CONTRACTOR

Holder Bingham

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

REPAIR



SIGNED

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

N^o

9507

REPAIROFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO,

DEC. 2

RECEIVED OF

VACANT HOUSE

FEE OF \$ 2

FOR WHICH PERMISSION IS GRANTED

GARY HOLDERBAUM

TO TAP

REPAIR SANITARY

SEWER ON THE

EAST

OF

6TH ST. SW.

AVE.

ST. TYPE OF STREET

ASPHALT

THE PREMISES BEING LOT NO.

1835

HOUSE NO.

112

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

GARY HOLDERBAUM

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.