

✓
✓
Nº 9513

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED

APRIL 28, 1983

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

119' FROM MH

HOUSE NO.

1033

SIZE OF PIPE USED

6"

up

DISTANCE FROM FIRST MANHOLE

DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

119' WEST OF MH 10' DEEP

WAS LATERAL AT CURB?


YES

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

MAKANITE

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

William Pappas

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

✓
Nº 9513

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, Feb 14

RECEIVED OF

Missy Bras

FEE OF \$ 25

FOR WHICH PERMISSION IS GRANTED

Missy Bras

TO TAP

Sanitary

SEWER ON THE

West

OF

Belmont St

AVE.

ST. TYPE OF STREET

City & Loc

THE PREMISES BEING LOT NO.

13712

, HOUSE NO.

1032

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Melville

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.