FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3 - 4 - 83	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? N MAT WAS ATTACHED TO MAIN SHOW BY DIAGRAM RELATION OF LATERAL TO WA	NAME OF CONTRACTOR PIAS
	er ale virth
	a service of the second
ea - OI	OCK!
SIGNED Welliem Hammer Inspector for City	FILED AT ENGINEER'S OFFICE

Nº 9517

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON, OHIO,	March	<u> </u>
RECEIVED OF Photograms	<i>F</i> .		FEE OF \$_ <u>26_5</u> _
FOR WHICH PERMISSION IS GRANTED // Lar/Larley	- F1-77-		
TO TAP Sant Frank SEV	VER ON THE	<u> </u>	·
OF AVE. ST. TY	PE OF STREET	<u> 128 ja 1 al</u>	Control Control
THE PREMISES BEING LOT NO. 17 3656	, Housi	E NO	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO OF THE DEPARTMENT OF PUBLIC SERVICE.			TY COUNCIL, AND
NAME OF CONTRACTOR		: 	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.