Nº 9520 ✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

HOUSE NO. 9 L4	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT 1161'S SUIT A SALE OF THE
SIZE OF PIPE USED	CURB LINE AND DEPTH 19' South of M 9'1
WAS LATERAL AT CURB? YES	NAME OF CONTRACTOR (5/1/C/
WAS ATTACHED TO MAIN	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
SHOW BY DIAGRAM RELATION OF LATERAL TO WA	DILIGIT SERVED. 1 22' K9'D N J
SIGNED William Hansana Inspector for City	FILED AT ENGINEER'S OFFICE

Nº 9520

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

3	MASSILLON, OHIO, 1947 9
K	RECEIVED OF JACOB GLICK FEE OF \$ 2
ST. N.E	FOR WHICH PERMISSION IS GRANTED JACOB 54/CK
1	TO TAP SA CHTARY SEWER ON THE EAST
•	OF CARNATION ST NEST. TYPE OF STREET CHIPY SEAC
	THE PREMISES BEING LOT NO. 14-07-5 , HOUSE NO. 964
	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.
X	NAME OF CONTRACTOR JACOB GLICK
111	Note: This permit covers work outside of building only. Any work

walls of building is subject to Massillon Board of Health Regulations.