Nº | 9526

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED U-10-83	IF SO HOW AND LOCATION FROM SO WEST OF MY 9'DEEP	
HOUSE NO. 610 ±		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? 10	 ,	
WAS ATTACHED TO MAIN VES	NAME OF CONTRACTOR $\frac{N/AS}{}$	_
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL		
SIGNED William Hamme inspector for City	FILED AT ENGINEER'S OFFICE	
REMARKS	· · · · · · · · · · · · · · · · · · ·	

Reluf Nº 9526

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

		оню <u>, Умереци /</u>	
RECEIVED OF Plan Et	Landelingey	<u> </u>	. FEE OF \$
FOR WHICH PERMISSION IS GRANTED JAMES A	7 / H .		
			·
TO TAP_ damidians	SEWER ON THE	<u> </u>	
OF		en,	
• •		f	
THE PREMISES BEING LOT NO. 4.114		HOUSE NO. R. 610	1. 41. 11 .
WORK TO BE DONE IN ACCORDANCE WITH ORDIN			
OF THE DEPARTMENT OF PUBLIC SERVICE.			
NAME OF CONTRACTOR		-	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.