

✓ ✓
Nº 9529

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6-16-83

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 2546

SIZE OF PIPE USED

6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

90' WEST OF H 8' DEEP

WAS LATERAL AT CURB?


YES

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

GERSTENLAGER

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

William Hamme
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 9529

OFFICE OF THE DIRECTOR OF PUBLIC SER
PERMIT TO TAP SEWER

MASSILLON, OHIO, June 10, 1971

RECEIVED OF

MARK WOUTAT

FEE OF \$ 2

FOR WHICH PERMISSION IS GRANTED

MARK WOUTAT

TO TAP

SEWTERY

SEWER ON THE

SOUTH

OF

TANGLE WOOD N.E.

AVE.

ST. TYPE OF STREET

THE PREMISES BEING LOT NO.

14023

, HOUSE NO.

2547

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

W. E. D. E. H. L. J. P. R.

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.