Nº 9535 CUT FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8-20-83	IF SO HOW AND LOCATION FROM	•
HOUSE NO. #17 4-45 E	FIRST MANHOLE DOWN STREAM	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?	NAME OF CONTRACTOR COLUMN	
SHOW BY DIAGRAM RELATION OF LATERAL TO WA	LL OF BUILDING SERVED.	:
Plagin	1 BASEMENT	· • • • • • • • • • • • • • • • • • • •
CVT Approximation		
SIGNED William Hames Inspector for City	FILED AT ENGINEER'S OFFICE	

Nº 9535

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

MASSILLON, OHIO, ADC.
FEE OF \$
sica Sower
/er on the
PE OF STREET
, HOUSE NO
0. 19.1971 DULY PASSED BY THE CITY COUNCIL, AN
···

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.