FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8-15-83	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 17/9	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT 29'WESTSFM 7'DEEP CURB LINE AND DEPTH
WAS LATERAL AT CURB? VES	NAME OF CONTRACTOR PIAS
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	and the second s
	N 151
	79.
will a glass	

REMARKS

 N^{0} 9539

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

3	MASSILLON, OHIO, AUGUST 15	
Trox	RECEIVED OF SIGHER CONSTRUCTION FEE OF \$	
po fr Wed	FOR WHICH PERMISSION IS GRANTED SIGNER CONSTACTION	
	TO TAP SANTALY SEWER ON THE SOUTH	
	OF AUP AND ST. TYPE OF STREET	
	THE PREMISES BEING LOT NO. 141 32 , HOUSE NO. 1719	·:
	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL,	, ANI
17/16	NAME OF CONTRACTOR 12.45 EXCAVA TILL	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.