

Nº 9554

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 11-9-83

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 546

SIZE OF PIPE USED 6" E 4"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? —

WAS ATTACHED TO MAIN —

NAME OF CONTRACTOR PLAS

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

REPAIR



SIGNED

William Hammer
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Repair
N^o 9554

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, *Nov 8*

RECEIVED OF *Plas Excavating* FEE OF \$ *25*

FOR WHICH PERMISSION IS GRANTED *Endicott*

TO TAP *Sanitary* SEWER ON THE *North*

OF *Heck Ave. S.W.* AVE. ST. TYPE OF STREET *Chip & Seal*

THE PREMISES BEING LOT NO. *5688*, HOUSE NO. *564*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Plas*

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.